

**[ LTO Memorandum Circular No. AVT-2015-1949,  
June 02, 2015 ]**

**USE OF THE SUPPLIED PLATE LOCKS FOR THE LTOMVPSP**

*Adopted: 02 June 2015  
Date Filed: 05 June 2015*

Relative to the implementation of LTO Motor Vehicle Plate Standardization Program (LTOMVPSP) wherein specially designed bolts/self tapping screws (Plate Locks) are issued for proper attachment of the license plate to a motor vehicle, failure to use the specified plate locks and/or the use of any other bolts/screws other than those supplied by the LTO -for the new standard license plate design shall constitute improper attachment thereof and shall be ground for being penalised with a fee of Php5,000.00 under **Section II(e) Joint Administrative Order No. 2014-01** dated 02 June 2014.

For strict compliance.

(SGD) ATTY. ALFONSO V. TAN, JR.  
*Assistant Secretary*



Source: Supreme Court E-Library

This page was dynamically generated by the E-Library Content Management System (E-LibCMS)