Factories (Shipbuilding and Ship-repairing) Regulations

Table of Contents

Part I PRELIMINARY

- 1 Citation
- 2 Definitions
- 3 Application
- **4 Obligations**
- 4A Ship repair manager to approve work
- 5 Equipment brought into shipyard or on board a ship in a harbour
- 6 Notification of work carried out on board a ship in a harbour

Part II GENERAL PROVISIONS

- 7 Disposal of debris
- 8 Equipment for personal protection
- 9 Falling hazards
- 10 Drowning hazards
- 11 Slipping hazards
- 12 Tripping and cutting hazards
- 13 Prevention of accidental closure of hatch
- 14 Prohibition of smoking
- 15 Spray painting

- 16 Metallic fumes
- 17 Ultra-violet radiation
- 18 Use of vehicles
- 19 Illumination of workplaces, etc.
- 20 Safety supervisor
- 21 Ship's safety co-ordinator
- 22 Safety orientation programme
- 23 Safety training course
- 23A Safety promotion exercise
- 24 Electrical safety
- 25 Safety measures and isolation of hazards
- 26 Ship repair manager
- 26A Ship repair manager to attend course

Part III VESSEL SAFETY CO-ORDINATION COMMITTEE

- 27 Vessel Safety Co-ordination Committee
- 28 Functions of Committee
- 29 Composition of Vessel Safety Co-ordination Committee
- 30 Meetings
- 31 Duties of Chairman
- **32 Duties of Secretary**

- 33 Frequency of meetings
- 34 Authorisation of hazardous work
- 34A Handing-over procedure for shifts

Part IV PERMIT-TO-WORK SYSTEM

- 35 Permit-to-work system
- 36 Procedures for application of permit-to-work
- 37 Issue, form and display of permit-to-work
- 38 Completion of work
- 39 Hot-work permit
- 40 Procedures for application of hot-work permit and inspection and assessment of hot-work area
- 41 Person carrying out hot-work to be competent in hot-work
- 42 Measures for hot-work
- 43 Marking of hot-work area
- 44 Fire watchman
- 45 Duty to report incompatible work
- 46 Duty to monitor hot-work
- 47 Validity of hot-work permit
- 48 Daily review and revocation of hot-work permit

Part V WELDING AND CUTTING OPERATIONS

- 49 Gas cylinders
- 50 Gas manifolds
- 51 Pipe lines and gas hoses
- 52 Gas equipment to be of good construction
- 53 Safety devices
- 54 Inspection of equipment
- 55 Safety measure during break in gas welding and cutting
- 56 Faulty or damaged equipment
- 57 Electrical installations and equipment
- 58 Arc welding machines
- 59 Inspection of welding equipment
- 60 No arc welding in wet conditions
- 61 Wetness to be dried before electric welding is carried out
- **62** Adequate ventilation
- 63 Welding and cutting on containers that held flammable substances

Part VI CONTROL OF HAZARDOUS MATERIAL

- 64 Approval of hazardous material
- 65 Material Safety Data Sheet and control of hazardous material
- 66 Warning signs
- 67 Labels

Part VII SAFETY INFORMATION AND AUDIT

- 68 Specification for industrial safety signs
- 69 Safety signs at suitable locations
- 70 Means of escape
- 71 Safety diary
- 72 Safety handbook
- 73 Safety management system
- 74 Safety audit
- 75 Implementation of auditor's recommendations

Part VIII SCAFFOLDS

- 76 Construction and materials
- 77 Supervision by scaffold supervisor
- 78 Duty of scaffold supervisor
- 79 Scaffold erectors
- 80 Inspection of scaffolds
- 81 Maintenance
- 82 Design and drawings of professional engineer required
- 83 Repair of damaged scaffolds
- 84 Scaffold to be free of all substances which endanger safety
- 85 Opening only for access